



Tech Info Library

Apple IIc Upgraded Motherboards: Diagnostics Error (9/95)

Revised: 9/19/95
Security: Everyone

Apple IIc Upgraded Motherboards: Diagnostics Error (9/95)

=====

Article Created: 20 January 1985
Article Reviewed/Updated: 19 September 1995

TOPIC -----

After an exchange of an upgraded Apple IIc motherboard, running old versions of the Apple IIc diagnostics results in an error condition, most frequently error code number 299.

DISCUSSION -----

The older versions of the diagnostics will not work properly with the upgraded motherboards. Use the most current version of Apple IIc diagnostics (at least Rev. C).

Article Change History:
19 Sep 1995 - Reformatted to meet current standards.
09 Nov 1988 - Reviewed for technical accuracy.

Support Information Services

Copyright 1988-95, Apple Computer, Inc.

Tech Info Library Article Number:1675