



Tech Info Library

Apple III: Interrupts and Reset on Peripheral Slots

Revised: 10/29/84
Security: Everyone

Apple III: Interrupts and Reset on Peripheral Slots

=====

The Apple III slots can not respond to IRQ or RESET from the peripheral cards in emulation mode. There is no way around it because the hardware is different. NMI is not on the same pin as in the Apple II and will act like RESET on the Apple II.

Apple Tech Notes

Tech Info Library Article Number:20